

CWEL Practice Test Questions and Answers

1. What does CWEL stand for in welding certification?

- A) Certified Welding Education Leader
- B) Canadian Welding Examination License
- C) Certified Welding Educator and Leader
- D) Canadian Welding Education and Leadership

2. Which welding process requires the most precise heat control for thin materials?

- A) Shielded Metal Arc Welding (SMAW)
- B) Gas Tungsten Arc Welding (GTAW/TIG)
- C) Gas Metal Arc Welding (GMAW/MIG)
- D) Flux-Cored Arc Welding (FCAW)

3. What is the primary cause of porosity in welded joints?

- A) Excessive welding current
- B) Contamination from moisture, oil, or inadequate shielding gas
- C) Improper joint preparation
- D) Incorrect travel speed

4. Which safety equipment is most critical when performing overhead welding?

- A) Safety glasses only
- B) Leather jacket and proper head protection
- C) Standard work gloves
- D) Hearing protection

Answers: 1-C 2-B 3-B 4-B

For More CWEL Questions and Answers FREE, CWEL Online Prep Training, CWEL Exam, CWEL Study Guide, CWEL Flashcards, CWEL Quizzes visit:

CWEL Practice Test